


APPENDIX E-1
Site Photographs - Cover Soil Area



Photograph No. 1. Site conditions at the potential cover soil source area located northeast of the main Gooseberry mine shaft (head frame in background). The track hoe is excavating Test-Pit No. TP-6. Photograph taken by AMEC personnel on February 2, 2006.



Photograph No 2A. Site conditions potential cover soil source area showing the track hoe excavating Test-Pit No. TP-11 located north of the heap leach pad. Photograph taken by AMEC personnel on February 3, 2006.



Photograph No. 2B. Site conditions at the potential cover soil target area looking north along Martin Canyon. Zones A and A2 are shown and correspond to the areas shown in Figure 2B. Photograph taken by AMEC personnel on February 3, 2006.

APPENDIX E-2
Site Photographs – Shaft Sites



Photograph No. 3. Site conditions at the main Gooseberry mine shaft showing the head frame, adjacent mine building, and bedrock exposed in the cut slope (lower left corner). Photograph taken by AMEC personnel on March 23, 2006.



Photograph No. 4. Site conditions at the (secondary) decline mine shaft showing the head frame, access roads, and adjacent small mine buildings. Photograph taken by AMEC personnel on March 22, 2006.



Photograph No. 5. Site conditions at the main Gooseberry mine shaft collar showing the locked cage (in yellow) and other steel structures. Photograph taken by AMEC personnel on March 23, 2006.



Photograph No. 6. Site conditions at the (secondary) decline shaft collar. Photograph taken by AMEC personnel on March 22, 2006.